



Configuring a Zebex 3220 BCR to add the tilde.

	Enter Config Mode
	Add Prefix
	Add Tilde
	Validate Prefix
	Set Prefix
	Add Suffix
	Add Enter
	Validate Suffix
	Set Suffix
	Exit Config Mode